



## 6970 47th Ave SW ~ Sewer Inspection

**Location**  
6970 47th Ave SW  
Seattle WA

**Inspector**  
Todd Vecchio  
Todd@SoundSewerinspection.com  
206-619-9990



3/19/2024

**Purpose:**

To video inspect the subject's lateral sewer line;  
Video of the sewer inspection is ready at: <https://youtube.com/watch?v=HNYWy4UCjd4>

**Quote:**

\$275 for the sewer inspection; An online invoice powered by PayPal was sent to the client.

**Recommended Action:**

Have the line jetted to remove the debris and standing water from the line.

**Summary:**

The subject has an updated PVC piped lateral sewer line that runs south off the property. The lateral sewer line is a shared line with three other properties and connects into the main city sewer line on SW Frontenac St. The PVC pipe is in good condition for a home of this age; no major issues to report. The line does have some debris in the shared line that can easily be cleaned out and washed down into the city main.



3/19/2024 8:58:10 AM

9"

Video out of the house is ready at: <https://youtube.com/watch?v=5UILLwszniOg>



3/19/2024 8:58:18 AM

2' 3"

Access to the sewer line located in the basement



3/19/2024 9:10:44 AM

8' 7"

Cast iron pipe connects with PVC pipe as the sewer line exits out of the house



3/19/2024 9:10:27 AM

17' 3"


Pipe turns south off the property



3/19/2024 9:10:03 AM

31' 8"

Updated PVC piped sewer line



3/19/2024 9:09:27 AM

52' 2"

Connection into the shared line with three other properties to the south and the east



3/19/2024 9:08:01 AM

99' 8"

Standing water due to debris in the shared line



3/19/2024 9:07:30 AM

114' 11"

Debris in the line



3/19/2024 9:06:31 AM

153' 0"

Pipe turns into the street



3/19/2024 9:05:53 AM

170' 4"

Video from the main city sewer line back to the house: <https://youtube.com/watch?v=HNYWy4UCjd4>